### **Nuclear Regulatory Commission**

§ 20.1901

these higher protection factors under the proposed conditions of use.

[64 FR 54557, Oct. 7, 1999]

## Subpart I—Storage and Control of Licensed Material

Source: 56 FR 23401, May 21, 1991, unless otherwise noted.

### §20.1801 Security of stored material.

The licensee shall secure from unauthorized removal or access licensed materials that are stored in controlled or unrestricted areas.

### § 20.1802 Control of material not in storage.

The licensee shall control and maintain constant surveillance of licensed


material that is in a controlled or unrestricted area and that is not in storage.

# Subpart J—Precautionary Procedures

Source:  $56\ \mathrm{FR}\ 23401,\ \mathrm{May}\ 21,\ 1991,\ \mathrm{unless}$  otherwise noted.

#### §20.1901 Caution signs.

(a) Standard radiation symbol. Unless otherwise authorized by the Commission, the symbol prescribed by this part shall use the colors magenta, or purple, or black on yellow background. The symbol prescribed by this part is the three-bladed design:



RADIATION SYMBOL

- (1) Cross-hatched area is to be magenta, or purple, or black, and
- (2) The background is to be yellow.